



VEHICLE INSPECTION REPORT

LL61KVZ

Mercedes-Benz SLK SLK 200 BlueEFFICIENCY 2dr Tip Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/11/2011	Keys	2	CAP Clean	£4,500.00
Year	2011	Service history	Yes	CAP Average	£3,900.00
Mileage	75,545 Miles Warranted	Service documents	Printout	CAP Below	£3,275.00
Fuel Type	PETROL	Number of stamps	13	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	10/07/2025	Gears	7
VIN	WDD1724482F016201	Last service miles	68,299	Doors	2
Body Style	Convertible	MOT Due	24/10/2026		

last service 10/7/25 @ 68,299 miles (13 services 4 main dealer) Service overdue

Tyres

NSF	BUDGET	4.0mm
NSR	TRIANGLE	4.0mm
OSF	BUDGET	3.0mm
OSR	TRIANGLE	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front armrest
- Steering wheel rake adjustment
- ABS
- Central locking
- Heated front seat
- Service indicator
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Wheel osr
Scratched
Up To 50mm



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Wheel nsr
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wheel nsf
Scratched
Up To 50mm



7: Bumper Front
Scratched
UpTo 25mm Thru Paint



8: Bonnet
Chipped
1 To 5



9: Roof
Poor Previous Repair
Paint Flake



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Seat Base Cover osf
Torn
Over 3mm



12: Bumper Front
Chipped
1 To 5



13: Door nsf
Dented
Between 10mm + 30mm



14: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

16: Door osf
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		