



VEHICLE INSPECTION REPORT

YD61PVT

Nissan Juke 1.6 DiG-T Tekna 5dr 4WD CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/09/2011	Keys	2	CAP Clean	£2,875.00
Year	2011	Service history	Yes	CAP Average	£2,400.00
Mileage	67,891 Miles Warranted	Service documents	Service Book	CAP Below	£1,925.00
Fuel Type	PETROL	Number of stamps	12	Gearbox	CVT
Colour	WHITE	Last service date	09/04/2026	Gears	1
VIN	JN1FANF15U0104629	Last service miles	66,085	Doors	5
Body Style	Hatchback	MOT Due	11/04/2027		

last service 9/4/26 @ 66,085 miles (12 services 1 main dealer) book & print Sd card reader or card faulty sat nav not working

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Over 30mm



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel osr
Chipped
1 To 5



10: Wheel osr
Scratched
Over 50mm




11: Door osr
Chipped
Edge Chip



12: Door osf
Chipped
Edge Chip



13: Wheel osf
Scratched
Over 50mm



14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



15: Other
N/A
N/A



16: A Post ns
Chipped
Over 5mm



17: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Fogdriving Lamp nsf
Broken
Replace



19: Seat Back Cover osf
Scuffed
UpTo 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK