



VEHICLE INSPECTION REPORT

YF09FYB

Volkswagen Polo 1.2 Match 60 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2009	Body Style	Hatchback	Last service miles	10,103
Year	2009	Keys	2	MOT Due	10/10/2026
Mileage	112,151 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	1	Doors	3
VIN	WVWZZZ9NZ9Y212875	Last service date	13/04/2010		

£50 ADDITIONAL FEE

MOT MILEAGE DISCREPANCY 07/07/2014

LAST SERVICE 13/04/2010 @ 10,103 MILES (1 SERVICE) One alloy wheel missing replaced by steel wheel

Eml light is on

Car been plugged in and detected

HO2S heater control circuit (bank 1, sensor 2)

Saggy roof lining

Tyres

NSF	FIRESTONE	5.0mm
NSR	LANDSAIL	5.0mm
OSF	ROTALLA	Damaged
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags

Photos





Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Other
N/A
N/A



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Dented
Over 30mm




8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



10: Sill ns
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: B Post ns
Dented
Between 10mm + 30mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Rusted
Over 5mm



15: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



16: Wheel osr
Scratched
Over 50mm




17: Door osf
Chipped
Over 5mm



18: Door osf
Dented
Between 10mm + 30mm



19: Sill os
Poor Previous Repair
Poor Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Poor Previous Repair
Poor Paint




22: Roof
Rusted
Over 5mm



23: Door Pad osf
Broken
Replace



24: Door Pad nsf
Scuffed
Over 25mm



25: Roof
Scratched
Over 25mm Thru Paint



26: Tyre osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK