



VEHICLE INSPECTION REPORT

GF68WBP

MG Mg 3 EXCLUSIVE VTI-TECH

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/11/2018	Body Style	Hatchback	Last service miles	47,839
Year	2018	Keys	1	MOT Due	21/12/2026
Mileage	65,032 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	4	Doors	5
VIN	SDPZ1CBDAJS131872	Last service date	04/12/2024		

£90 ADDITIONAL FEE

Last service 04/12/2024 at 47,839 miles- 4 services (2 main dealer) Exhaust blowing

Tyres


NSF	KUMHO	6.0mm
NSR	NEXEN	5.0mm
OSF	KUMHO	6.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Central locking
- PAS
- Digital radio
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking

Photos






Condition Check




Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Poor Previous Repair
Rippled UpTo 30%



6: Door nsr
Poor Previous Repair
Rippled UpTo 30%



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Qtr Panel osr
Scratched
Over 25mm Thru Paint




11: Wheel osr
Scratched
Over 50mm



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
Over 30mm



14: Door osf
Scratched
UpTo 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Dented
Between 10mm + 30mm



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Screen Front
Cracked
Replace



19: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK