



VEHICLE INSPECTION REPORT

GU60DXS

Honda CR-V 2.0 i-VTEC SE-T 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/09/2010	Body Style	Estate	Last service miles	71,488
Year	2010	Keys	1	MOT Due	17/08/2026
Mileage	82,566 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	6	Doors	5
VIN	SHSRE5830AU016841	Last service date	14/08/2023		

Last Service - 14.08.2023 at 71488 miles (6 services)

Tyres


NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
1 To 5



8: Door nsr
Poor Previous Repair
Rippled Up To 30%



9: C Post ns
Poor Previous Repair
Poor Paint



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Bumper Rear
Dented
With Paint Damage



12: Tailgate
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5



14: Door osr
Chipped
Edge Chip



15: Door osr
Dented
Between 10mm + 30mm



16: Door osr
Chipped
Edge Chip



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Dented
With Paint Damage



20: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK