



VEHICLE INSPECTION REPORT

RO60XGJ

Renault Clio 1.2 TCE Dynamique TomTom 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 31/01/2011

Year 2011

Mileage 91,075 Miles
Warranted

Fuel Type PETROL

Colour SILVER

VIN VF1BRC40H44731583

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 7

Last service date 25/04/2019

Last service miles 60,845

MOT Due 05/03/2027

Gearbox MANUAL

Gears 5

Doors 5

last service 25/4/19 @ 60,845 miles (7 main dealer)

Tyres

NSF BUDGET 5.0mm

NSR ACCELERA 5.0mm

OSF BUDGET 5.0mm


OSR SUNNY 6.0mm

Spare

Features


- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Metallic Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Dented
UpTo 30mm (Alloy)



2: Door Moulding of
Scratched (Painted)
UpTo 25mm Thru Paint




3: Door osr
Dented
Between 10mm + 30mm



4: Qtr Panel osr
Dented
Over 30mm



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Scratched
Over 100mm Thru Paint




7: Tailgate
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage




9: Wheel nsr
Scratched
Over 50mm




10: Door nsr
Dented
Between 10mm + 30mm



11: Door Moulding nsr
Scratched (Painted)
UpTo 25mm Thru Paint



12: Door Moulding nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Door nsf
Chipped
1 To 5



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm




16: Wing nsf
Chipped
1 To 5



17: Bumper Front
Chipped
1 To 5



18: Screen Front
Cracked
Replace



19: Seat Base Cover osf
Torn
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK