



VEHICLE INSPECTION REPORT

GU64JYA

Citroen C3 1.2 VTi VTR+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/09/2014	Body Style	Hatchback	Last service miles	70,924
Year	2014	Keys	1	MOT Due	27/09/2026
Mileage	72,070 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	12	Doors	5
VIN	VF7SCHMZ0EW631485	Last service date	08/06/2026		

last service 8/6/26 @ 70,924 miles (12 services 3 main dealer) book & print Exhaust blowing

Tyres


NSF	BUDGET	4.0mm
NSR	KUMHO	5.0mm
OSF	BUDGET	4.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Chipped
1 To 5



6: Door nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Chipped
1 To 5




10: Door osr
Dented
Between 10mm + 30mm




11: Door osr
Chipped
1 To 5



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Up To 50mm



16: Wheel nsr
Scratched
Up To 50mm



17: Roof
Chipped
1 To 5



18: Aperture Seal nsr
Broken
Replace



19: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK