

# VEHICLE INSPECTION REPORT

**LY19HDE**

## Suzuki Jimny 1.5 SZ5 ALLGRIP Auto 3dr

| Inspection      |    | Vehicle |        |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT     | Margin |
|                 |    | V5      | TBC    |

nama  
GRADE  
**2**

### Details

|           |                           |            |                   |             |            |
|-----------|---------------------------|------------|-------------------|-------------|------------|
| Reg. date | 13/03/2019                | VIN        | JSAGJB74V00107349 | CAP Average | £19,150.00 |
| Year      | 2019                      | Body Style | Estate            | CAP Below   | £17,750.00 |
| Mileage   | 47,957 Miles<br>Warranted | Keys       | 2                 | Gearbox     | AUTOMATIC  |
| Fuel Type | Petrol                    | MOT Due    | 21/02/2026        | Gears       | 4          |
| Colour    | WHITE                     | CAP Clean  | £20,550.00        |             |            |

£65 ADDITIONAL FEE.


### Tyres

|       |             |       |
|-------|-------------|-------|
| NSF   | HANKOOK     | 5.0mm |
| NSR   | HANKOOK     | 6.0mm |
| OSF   | HANKOOK     | 5.0mm |
| OSR   | BRIDGESTONE | 5.0mm |
| Spare |             |       |

## Features


- Bluetooth connection
- PAS
- Digital radio
- Front electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Audio remote control
- Climate control
- Solid Paint
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos




1: Boot Lid  
Dented  
With Paint Damage




2: Qtr Panel or  
Chipped  
1 To 5



3: Door osf  
Chipped  
1 To 5



4: Door osf  
Scratched  
Over 25mm Not Thru Paint




5: Wing osf  
Scratched  
Over 25mm Not Thru Paint



6: Bonnet  
Chipped  
1 To 5



7: Wing nsf  
Chipped  
1 To 5



8: Door nsf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |  |    |
| Windows                  | OK | Radio  | OK |
| Sat nav                  | OK | Steering                                       | OK |