



VEHICLE INSPECTION REPORT

YE19FMG

Seat Leon 2.0 TSI 190 FR [EZ] 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
2

Details

Reg. date	21/03/2019	VIN	VSSZZZ5FZKR059926	CAP Average	£11,200.00
Year	2019	Body Style	Estate	CAP Below	£10,100.00
Mileage	27,951 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Petrol	MOT Due	11/10/2025	Gears	7
Colour	RED	CAP Clean	£12,300.00		


£65 ADDITIONAL FEE.

Tyres		
NSF	BRIDGESTONE	3.0mm
NSR	BUDGET	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



5: Wheel nsr
Scratched
Up To 50mm



6: Door nsr
Chipped
1 To 5



7: Door nsf
Dented
2 Or Less UpTo 10mm

No Image


8: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Bonnet
Chipped
1 To 5



11: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Wheel osf
Scratched
Up To 50mm



14: Door osf
Chipped
1 To 5

No Image

No Image

15: Door osf
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

16: Door osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK