



VEHICLE INSPECTION REPORT

OY16AKF

Land Rover Discovery Sport 2.0 TD4 180 HSE Luxury 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	07/03/2016	Body Style	Estate	Last service miles	99,101
Year	2016	Keys	2	MOT Due	Expired
Mileage	99,636 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	9
Colour	BROWN	Number of stamps	5		
VIN	SALCA2AN0GH600862	Last service date	22/05/2025		

£65 ADDITIONAL FEE Last service 22/05/2025 @ 99101 miles (5 SERVICES 3 MAIN DEALER)

Tyres

NSF	BUDGET	2.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Audio remote control
- Electric sunroof
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Towbar
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Over 50mm

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm

No Image

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Wheel nsf
Scratched
Over 50mm



10: Bonnet
Chipped
1 To 5



11: Bumper Front
Chipped
Multiple Chips



12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5



15: Door osf
Chipped
1 To 5



16: Door osr
Chipped
1 To 5



17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		