



VEHICLE INSPECTION REPORT

GY640BE

Nissan Juke 1.2 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/11/2014	Body Style	Hatchback	MOT Due	28/11/2026
Year	2014	Service history	Yes	Gearbox	MANUAL
Mileage	48,131 Miles Warranted	Service documents	Printout	Gears	5
Fuel Type	PETROL	Number of stamps	4	Doors	5
Colour	GREY	Last service date	23/11/2018		
VIN	SJNFEAF15U7065745	Last service miles	13,477		

£100 ADDITIONAL FEE

Last service 23/11/2018 at 13,477 miles- 4 main dealer services Noisy engine

Tyres



NSF	BRIDGESTONE	5.0mm
NSR	COOPER TIRES	6.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alarm
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel of front left
Scratched
Over 50mm



2: Wheel of front right
Scratched
Over 50mm



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Wheel nsr
Corroded
Light



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Wheel Trim osr
Scratched
Over 50mm



11: Wheel osr
Corroded
Light



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK