



VEHICLE INSPECTION REPORT

HV64WNX

Honda Civic 1.8 i-VTEC S 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	27/01/2015	Body Style	Hatchback	Last service miles	68,165
Year	2015	Keys	2	MOT Due	28/01/2027
Mileage	113,101 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	7	Doors	5
VIN	SHHFK3790EU210493	Last service date	19/02/2022		

£100 ADDITIONAL FEE

LAST SERVICE 19/02/2022 @ 68,165 MILES (7 SERVICES, 6 MAIN DEALER)

HPI PULLS THROUGH AS AN AUTOMATIC.

Tyres


NSF	GT RADIAL	6.0mm
NSR	KUMHO	5.0mm
OSF	GT RADIAL	6.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
With Paint Damage



5: Sill ns
Dented
Over 30mm



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm




9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
With Paint Damage



12: Door osf
Chipped
Edge Chip



13: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK