



VEHICLE INSPECTION REPORT

HX66UAG

Kia Picanto 1.25 Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2016	Body Style	Hatchback	Last service miles	69,443
Year	2016	Keys	2	MOT Due	31/08/2026
Mileage	69,527 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	5	Doors	5
VIN	KNABX512LHT304616	Last service date	26/06/2026		

£100 ADDITIONAL FEE

Last Service - 26.06.2026 at 69443 miles (5 services) Low clutch

Stop start not available message displayed

Tyres


NSF	SUNNY	5.0mm
NSR	HANKOOK	5.0mm
OSF	SUNNY	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsf
Dented
2 Or Less UpTo 10mm



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Bumper Rear
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Dented
Between 10mm + 30mm



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK