



VEHICLE INSPECTION REPORT

MF66XOL

Kia Sportage 1.6 GDi 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2016	Body Style	Estate	Last service miles	67,539
Year	2016	Keys	2	MOT Due	15/10/2026
Mileage	69,886 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	1	Doors	5
VIN	U5YPG814LGL156904	Last service date	17/03/2026		

£100 ADDITIONAL FEE

last service 17/3/26 @ 67,539 miles (1 service) Soiled seats
Low clutch

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm




4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Poor Previous Repair
Rippled UpTo 30%



8: Door nsr
Chipped
Multiple Chips



9: Door nsr
Dented
Over 30mm



10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
Between 10mm + 30mm




15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Chipped
Multiple Chips



17: Wing osf
Chipped
1 To 5



18: Door osf
Dented
Over 30mm



19: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK