



VEHICLE INSPECTION REPORT

YS65UMH

Hyundai Tucson 2.0 CRDi SE Nav 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/12/2015	Body Style	Estate	Last service miles	52,503
Year	2015	Keys	2	MOT Due	05/10/2026
Mileage	79,485 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	TMAJ381ASGJ092428	Last service date	12/08/2024		

£90 ADDITIONAL FEE

Last service 12/08/2024 at 52,503 miles- 2 services Reverse camera faulty

Tyres



NSF	BUDGET	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet Chipped Multiple Chips




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Bumper Rear Moulding
Broken
Replace



12: Tailgate
Dented
With Paint Damage



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Dented
Between 10mm + 30mm



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
UpTo 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



22: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK