



VEHICLE INSPECTION REPORT

BT67UXF

Peugeot 3008 1.6 BlueHDi 120 GT Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/12/2017	Body Style	Hatchback	Last service miles	102,895
Year	2017	Keys	2	MOT Due	29/07/2027
Mileage	102,916 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	9	Doors	5
VIN	VF3MCBHZHHS364324	Last service date	10/07/2026		

Last service 10/07/2026 at 102,895 miles- 9 services (6 main dealer) Eml light on car has been plugged in and detects no codes

Tyres

NSF	SAILUN	3.0mm
NSR	SAILUN	5.0mm
OSF	SAILUN	3.0mm
OSR	SAILUN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Alarm
- Cruise control
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Trip computer
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Rear wiper
- Radio/CD
- Roof rails
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Blind spot information
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
UpTo 25mm




3: Wheel nsf
Scratched
Over 50mm



4: A Post ns
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Between 10mm + 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel osr
Dented
Between 10mm + 30mm



9: Wheel osr
Corroded
Light




10: Door osr
Poor Previous Repair
Rippled UpTo 30%



11: Door osf
Dented
Between 10mm + 30mm



12: Wheel osf
Scratched
Over 50mm



13: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		