



VEHICLE INSPECTION REPORT

GY66CEU

Volkswagen Golf 2.0 TDI R-Line Edition 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/09/2016	Body Style	Hatchback	MOT Due	27/11/2026
Year	2016	Keys	2	Gearbox	SEMI AUTO
Mileage	78,264 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	DIESEL	Number of stamps	4	Doors	5
Colour	GREY	Last service date	13/08/2026		
VIN	WWWZZZAUZGW287322	Last service miles	44,224		

£90 ADDITIONAL FEE

Engine noisy

EML light on car has been plugged in but will show no code

Tyres


NSF	FIRESTONE	4.0mm
NSR	BUDGET	5.0mm
OSF	FIRESTONE	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Seat Back Cover osf
Torn
Over 3mm



3: Wheel osf
Corroded
Light



4: Wing osf
Chipped
1 To 5



5: Other
N/A
N/A



6: Door osf
Chipped
Edge Chip




7: Wheel osr
Corroded
Light



8: Qtr Panel osr
Dented
Between 10mm + 30mm



9: Other
N/A
N/A



10: Bumper Rear
Chipped
Multiple Chips




11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Qtr Panel nsr
Dented
Over 30mm



13: Wheel nsr
Corroded
Light




14: Door nsr
Dented
Between 10mm + 30mm



15: Door nsr
Scratched
UpTo 25mm Thru Paint



16: Door nsf
Chipped
Edge Chip



17: Door nsf
Chipped
1 To 5



18: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



19: Wheel nsf
Corroded
Light



20: Bumper Front
Scratched
Over 100mm Thru Paint



21: Bonnet
Chipped
1 To 5



22: Screen Front
Cracked
Replace



23: Roof
Scratched
Over 25mm Thru Paint



24: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		