



VEHICLE INSPECTION REPORT

WK66WSF

Kia Sportage 1.7 CRDi ISG 3 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

nama
GRADE
3

Details

Reg. date	15/11/2016	Body Style	Estate	Last service miles	65,263
Year	2016	Keys	2	MOT Due	Expired
Mileage	186,064 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	U5YPH815LGL190316	Last service date	06/04/2021		

£100 ADDITIONAL FEE

Last service 06/04/2021 at 65,263 miles- 6 services (4 main dealer)

MOT EXPIRED Service overdue

Struggling to get in gears

Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Corroded
Light



7: Door osr
Chipped
Edge Chip



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear
Chipped
1 To 5



10: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



11: Wheel nsr
Corroded
Light



12: Door nsr
Dented
2 Or Less UpTo 10mm



13: Door nsf
Scratched
UpTo 25mm Thru Paint



14: Wheel nsf
Corroded
Light



15: Wing nsf
Chipped
1 To 5



16: Bumper Front
Chipped
Multiple Chips



17: Bonnet
Chipped
Multiple Chips



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Chipped
1 To 5



20: Door osf
Dented
Between 10mm + 30mm



21: Tailgate
Dented
Over 30mm



22: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK