



VEHICLE INSPECTION REPORT

GU58BVA

Inspection

Vehicle

nama
GRADE
4

VAT	Margin
V5	Present

Details

Reg. date	12/09/2008	Keys	2	CAP Clean	£850.00
Year	2008	Service history	Yes	CAP Average	£350.00
Mileage	110,992 Miles Warranted	Service documents	Service Book	CAP Below	£250.00
Fuel Type	DIESEL	Number of stamps	16	Gearbox	MANUAL
Colour	GREY	Last service date	06/09/2024	Gears	5
VIN	WVWZZZ1KZ8W536405	Last service miles	106,140	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£100 ADDITIONAL FEE

Last service 06/09/2024 at 106,140 miles- 16 services (3 main dealer) Book and print

Clutch replaced 12/11/2021 at 63,341 miles

MOT EXPIRED Heater blowers do not work

Osf window does not open

Tyres

NSF	FULLRUN	4.0mm
NSR	FALKEN	6.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



3: Door osf
Dented
Over 30mm



4: Door osr
Dented
Between 10mm + 30mm



5: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint



6: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



8: Qtr Panel osr
Rusted
Over 5mm



9: Wheel osr
Corroded
Light



10: Lamp osr
Broken
Replace



11: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Chipped
1 To 5



14: Qtr Panel nsr
Dented
Over 30mm



15: Wheel nsr
Scratched
Over 50mm




16: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



17: Door nsr
Chipped
1 To 5



18: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



19: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



20: Door nsf
Chipped
Edge Chip



21: Other
N/A
N/A



22: Wing nsf
Scratched
UpTo 25mm Thru Paint



23: Wheel nsf
Scratched
Over 50mm



24: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



25: Bumper Front
Scratched
Over 100mm Thru Paint



26: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	Fault	Radio	OK
		Steering	OK