



VEHICLE INSPECTION REPORT

GC16CDY

Dacia Duster 1.5 dCi 110 Laureate 5dr 4X4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2016	Keys	2	CAP Clean	£2,625.00
Year	2016	Service history	Yes	CAP Average	£2,175.00
Mileage	116,213 Miles Warranted	Service documents	Service Book	CAP Below	£1,725.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	WHITE	Last service date	01/06/2024	Gears	6
VIN	UU1HSDJ9N55004180	Last service miles	99,624	Doors	5
Body Style	Hatchback	MOT Due	29/06/2025		

Last Service - 01.06.2024 at 99624 miles (7 services)
Clutch + Dual Mass Flywheel Replaced 10.07.2024 @ 99624 miles
Timing belt + Water Pump Replaced 30.12.2023 @ 91125 miles Missing a rear headrest

Tyres

NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	RAPID	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Digital radio
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Over 50mm



7: Door osf
Chipped
1 To 5

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Door osr
Dented
Over 30mm



8: Wing osf
Scratched
UpTo 25mm Thru Paint



9: Wheel osf
Scratched
Up To 50mm



10: Bonnet
Dented
With Paint Damage




11: Bumper Front
Chipped
Multiple Chips



12: Wheel nsf
Scratched
Up To 50mm



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Door nsf
Scratched
Over 25mm Not Thru Paint



15: Door nsr
Dented
Between 10mm + 30mm



16: Wheel nsr
Scratched
Up To 50mm



17: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK