



VEHICLE INSPECTION REPORT

YG59BDV

Vauxhall Zafira 1.9 CDTi Elite [120] 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/01/2010	Keys	2	CAP Clean	£770.00
Year	2010	Service history	Yes	CAP Average	£370.00
Mileage	135,870 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	18/09/2024	Gears	6
VIN	W0LOAHM75A2049164	Last service miles	133,938		
Body Style	MPV	MOT Due	27/09/2025		

Last Service - 18.09.2024 at 133938 miles (11 main dealer services)

Tyres

NSF	MAXTREK	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Fixed panoramic glass roof
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint




13: Boot Lid
Scratched
Over 25mm Not Thru Paint




14: Qtr Panel osr
Chipped
1 To 5



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osr
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK