



# VEHICLE INSPECTION REPORT

**AF65TYV**

## Volvo V40 D2 [120] Cross Country Lux 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/10/2015	Keys	2	CAP Clean	£5,300.00
Year	2015	Service history	Yes	CAP Average	£4,525.00
Mileage	79,234 Miles Warranted	Service documents	Service Book	CAP Below	£3,775.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	AUTOMATIC
Colour	RED	Last service date	25/02/2025	Gears	6
VIN	YV1MZ74L0G2091140	Last service miles	78,166	Doors	5
Body Style	Hatchback	MOT Due	27/08/2025		

Last Service - 25.02.2025 at 78166 miles (6 services)

### Tyres

NSF	TOYO	2.0mm
NSR	BLACKLION	3.0mm
OSF	TOYO	4.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Chipped  
1 To 5

No Image



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint

8: Wheel nsr  
Scratched  
Up To 50mm




9: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



10: Bumper Rear  
Chipped  
Multiple Chips



11: Wheel osr  
Scratched  
Up To 50mm



12: Door osr  
Scratched  
Over 25mm Not Thru Paint



13: Door Moulding osf  
Scratched (Painted)  
Over 25mm Not Thru Paint



14: Wing osf  
Scratched  
Over 25mm Not Thru Paint



15: Wheel of  
Scratched  
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK