

VEHICLE INSPECTION REPORT

YE66KMG

Hyundai Ioniq 1.6 GDi Hybrid Premium SE 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/10/2016	Keys	2	CAP Clean	£8,275.00
Year	2016	Service history	Yes	CAP Average	£7,275.00
Mileage	69,475 Miles Warranted	Service documents	Service Book	CAP Below	£6,300.00
Fuel Type	Hybrid Electric	Number of stamps	7	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	24/10/2024	Gears	6
VIN	KMHC851CVHU010265	Last service miles	65,902	Doors	5
Body Style	Hatchback	MOT Due	30/10/2025		

Last Service -24.10.2024 at 65902 miles (7 services) Parking sensor fault

Tyres


NSF	BUDGET	3.0mm
NSR	NEXEN	3.0mm
OSF	RAPID	4.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Trip computer
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Steel wheels
- Navigation system
- Steering wheel mounted controls
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Thru Paint

No Image

3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



4: Door nsr
Chipped
1 To 5

No Image

5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint




8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Bonnet
Chipped
1 To 5



10: Bumper Front
Chipped
Multiple Chips




11: Bumper Front
Scratched
Over 25mm Not Thru Paint



12: Wing osf
Chipped
1 To 5



13: Door osf
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



15: Door osr
Scratched
Over 25mm Not Thru Paint

16: Qtr Panel osr
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK