



VEHICLE INSPECTION REPORT

WX63TVU

Kia Rio 1.4 CRDi 2 EcoDynamics 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	11/09/2013	Keys	1	CAP Clean	£1,875.00
Year	2013	Service history	Yes	CAP Average	£1,475.00
Mileage	64,953 Miles Warranted	Service documents	Printout	CAP Below	£1,075.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	17/05/2024	Gears	6
VIN	KNADN514LE6881982	Last service miles	57,769	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£100 ADDITIONAL FEE Last service 17/05/2024 @ 57769 miles (2 SERVICES) EML LIGHT ON
DRIVERS WINDOW SWITCH BROKEN
LOW CLUTCH

Tyres

NSF

NSR	CONTINENTAL	3.0mm
OSF	AVON	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Carpets Front
Holed
Over 3mm




2: Wing osf
Chipped
Over 5mm



3: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip




5: Door osr
Scratched
Over 25mm Thru Paint




6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Door nsr
Chipped
Edge Chip



9: Door nsr
Chipped
1 To 5



10: Door nsr
Dented
Between 10mm + 30mm



11: Door nsf
Poor Previous Repair
Paint Flake



12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK