



VEHICLE INSPECTION REPORT

GL62XGB

Peugeot 3008 1.6 VTi Active II 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/02/2013	Body Style	Hatchback	Last service miles	60,927
Year	2013	Keys	2	MOT Due	22/11/2026
Mileage	72,384 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Electronic / Online	Gears	5
Colour	RED	Number of stamps	2	Doors	5
VIN	VF30U5FS0DS014397	Last service date	22/11/2023		

LAST SERVICE 22/11/2023 @ 60,927 MILES (2 SERVICES, CONFIRMED BY WALKERS GARAGE, SALE)
Eml light is on car been plugged in and detected intake camshaft dephasure

Tyres


NSF	PACE	5.0mm
NSR	BUDGET	4.0mm
OSF	PACE	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Service indicator
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Corroded
Light




4: Door nsf
Dented
With Paint Damage



5: A Post ns
Chipped
1 To 5



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsr
Scratched
UpTo 25mm Thru Paint




8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




10: Wheel osr
Scratched
Up To 50mm




11: Door osr
Chipped
1 To 5




12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Up To 50mm



16: Roof
Dented
Over 30mm



17: Fascia Trim
Missing
Replace



18: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK