



VEHICLE INSPECTION REPORT

GU09DZZ

Honda Jazz 1.4 i-VTEC ES 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/03/2009	Keys	2	CAP Clean	£1,225.00
Year	2009	Service history	Yes	CAP Average	£840.00
Mileage	115,503 Miles Warranted	Service documents	Service Book	CAP Below	£425.00
Fuel Type	PETROL	Number of stamps	7	Gearbox	MANUAL
Colour	BLUE	Last service date	24/05/2021	Gears	5
VIN	JHMGE67609S206359	Last service miles	85,705	Doors	5
Body Style	Hatchback	MOT Due	Expired		

MOT EXPIRED

LAST SERVICE 24/05/2021 @ 85,705 MILES (7 SERVICES) Both rear windows do not work

Steering goes heavy then loose

Tyres

NSF	TOYO	4.0mm
NSR	BUDGET	5.0mm
OSF	TOYO	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Metallic Paint
- Central locking
- Radio/CD
- Front electric windows
- ABS
- Remote central locking
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Dented
Between 10mm + 30mm



6: Wheel osr
Scratched
Over 50mm



7: Door osr
Chipped
Edge Chip



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear
Chipped
Multiple Chips



10: Tailgate
Poor Previous Repair
Poor Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Door nsr
Chipped
1 To 5



14: Door nsf
Chipped
1 To 5



15: Door Mirror Assy nsf
Broken
Replace



16: Wheel nsf
Scratched
Over 50mm



17: Wing nsf
Scratched
UpTo 25mm Thru Paint



18: Bonnet
Chipped
Multiple Chips



19: Bumper Front
Chipped
Multiple Chips



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	Fault