



# VEHICLE INSPECTION REPORT

**KS65XJV**

## Nissan Qashqai 1.5 dCi N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/01/2016	Service history	Yes	CAP Average	£3,750.00
Year	2016	Service documents	Service Book	CAP Below	£3,150.00
Mileage	93,467 Miles Warranted	Number of stamps	7	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	31/01/2025	Gears	6
Colour	BLACK	Last service miles	90,674	Doors	5
VIN	SJNFAAJ11U1542554	MOT Due	19/02/2026		
Body Style	Hatchback	CAP Clean	£4,325.00		

Last Service: 31/01/2025 at 90674 miles. (7 main dealer services ) Stiff to get into gear

### Tyres

NSF	NEXEN	3.0mm
NSR	FALKEN	5.0mm
OSF	NEXEN	3.0mm
OSR	FALKEN	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm

No Image



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Dented  
With Paint Damage

No Image

No Image

7: Door nsr  
Scratched  
Over 25mm Not Thru Paint

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Corroded  
Light



10: Wing osf  
Chipped  
1 To 5



11: Wing osf  
Scratched  
Over 25mm Not Thru Paint



12: Wheel osf  
Scratched  
Over 50mm



13: Door osf  
Dented  
Over 2 UpTo 10mm



14: Door osf  
Scratched  
Over 25mm Not Thru Paint



15: Door osr  
Dented  
Over 2 UpTo 10mm

No Image

16: Door osf  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osr  
Scratched  
Over 50mm

No Image

18: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



19: Bumper Rear  
Chipped  
Multiple Chips

No Image

20: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint





21: Boot Lid  
Dented  
Over 2 UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		