

VEHICLE INSPECTION REPORT

PN64ZKJ

Nissan Qashqai 1.5 dCi Tekna 5dr

Inspection		venicie			nama
Serious Damage?	No	VAT	Margin		
		V5	Present		
Details					
Reg. date	18/09/2014	Keys	2	CAP Clean	£5,100.00
Year	2014	Service history	Yes	CAP Average	£4,425.00
Mileage	69,860 Miles	Service documents	Service Book	CAP Below	£3,775.00
	Warranted	Number of stamps	10	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	10/09/2024	Gears	6
Colour	GREY	Last service miles	67,392	Doors	5
VIN	SJNFAAJ11U1195493	MOT Due	17/09/2025		
Body Style	Hatchback		,,		

Last Service: 10/09/2024 at 67392 miles. (10 main dealer services)

NSF	ROADSTONE	4.0mm	
NSR	GOODYEAR	4.0mm	
OSF	ROADSTONE	4.0mm	
OSR	GOODYEAR	5.0mm	
Spare		,	

Features

- Bluetooth connection
- PAS
- Digital radioFixed panoramic glass roofFront armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
 Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
 Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

- Navigation system
 Steering wheel mounted controls
 Electric door mirrors

 Park assist camera
 Audio remote control
 Electric sunroof
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag Traction control
- Alloy wheels

- Electrically adjustable drivers seat
 Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper From Chipped Multiple Chips



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5



5: Door nsf Chipped 1 To 5



6: Door nsr Chipped 1 To 5



7: Wheel nsr Scratched Over 50mm

No Image

8: Qtr Panel nsr Scratched Over 25mm Not Thru Paint

PN64ZKJ

9: Bumper Rear Chipped Multiple Chips

No Image

10: Boot Lid Scratched Over 25mm Not Thru Paint



11: Door osr Dented Over 2 UpTo 10mm



12: Door osf Chipped 1 To 5



13: Wing osf Chipped 1 To 5



14: Wheel osr Scratched Over 50mm



15: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		