



# VEHICLE INSPECTION REPORT

**GJ23MJE**

## Dacia Jogger 1.0 TCe Expression 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                           |                   |              |                    |            |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 07/03/2023                | Body Style        | MPV          | Last service miles | 17,159     |
| Year      | 2023                      | Keys              | 2            | MOT Due            | 06/03/2027 |
| Mileage   | 31,058 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | Petrol                    | Service documents | Service Book | Gears              | 6          |
| Colour    | WHITE                     | Number of stamps  | 2            |                    |            |
| VIN       | UU1DJF00670186122         | Last service date | 19/02/2025   |                    |            |

£90 ADDITIONAL FEE

last service 19/2/25 @ 17,159 miles (2 services) book & print

Date of service at 8608 miles not recorded Check anti pollution system

Service spanner displayed

### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | FALKEN  | 5.0mm |
| NSR   | HANKOOK | 5.0mm |
| OSF   | BUDGET  | 6.0mm |
| OSR   | KUMHO   | 5.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel Trim nsf  
Missing  
Replace



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Chipped  
1 To 5



6: Door nsf  
Dented  
Over 30mm



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Tailgate  
Dented  
Over 30mm



9: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



10: Door osf  
Dented  
Over 30mm



11: Wing osf  
Chipped  
1 To 5

### Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

### Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

|               |    |                                                |    |
|---------------|----|------------------------------------------------|----|
| Engine Runs   | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes        | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
|               |    | No Excessive Smoking                           | OK |

|                          |    |                                     |       |
|--------------------------|----|-------------------------------------|-------|
| EML light illuminated    | OK | Oil warning light illuminated       | OK    |
| Airbag light illuminated | OK | Service indicator light illuminated | Fault |
| ABS light illuminated    | OK |                                     |       |
| Windows                  | OK | Radio                               | OK    |
|                          |    | Steering                            | OK    |