



VEHICLE INSPECTION REPORT

KR70BCZ

Land Rover Range Rover Velar 2.0 D240 R-Dynamic HSE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	09/10/2020	Body Style	Estate	Last service miles	20,518
Year	2020	Keys	2	MOT Due	Expired
Mileage	48,746 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	1	Doors	5
VIN	SALYA2AN2LA289296	Last service date	26/05/2023		

£90 ADDITIONAL FEE

MOT EXPIRED

LAST SERVICE 26/05/2023 @ 20,518 MILES (1 SERVICE, MAIN DEALER)

Tyres


NSF	MICHELIN	2.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Chipped
1 To 5



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Dented
With Paint Damage



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Poor Previous Repair
Paint Flake



12: Other
N/A
N/A



13: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		