



VEHICLE INSPECTION REPORT

GX20HGC

Ford Puma 1.0 EcoBoost Hybrid mHEV 155 ST-Line X 1st Ed 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/07/2020	Body Style	Hatchback	Last service miles	11,159
Year	2020	Keys	2	MOT Due	03/07/2027
Mileage	71,367 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	WF02XXERK2LB46028	Last service date	04/06/2024		

£100 ADDITIONAL FEE

Last Service - 04.06024 at 11159 miles (2 services) Ex drivers lesson school car

Tyres

NSF	CONTINENTAL	5.0mm
NSR	ACCELERA	5.0mm
OSF	BUDGET	4.0mm
OSR	ACCELERA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm




4: Door nsf
Dented
Between 10mm + 30mm




5: Sill ns
Scratched
Up To 25mm Thru Paint



6: Wheel nsr
Scratched
Up To 50mm




7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Door osr
Chipped
1 To 5



9: Roof
Scratched
Over 25mm Not Thru Paint



10: Door osf
Chipped
Edge Chip



11: Door osf
Dented
Over 30mm



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK