



VEHICLE INSPECTION REPORT

GJ60OFH

Kia Soul 1.6 CRDi Echo 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	20/10/2010	VIN	KNAJT813LB7201597	Gearbox	MANUAL
Year	2010	Body Style	Hatchback	Gears	5
Mileage	112,581 Miles Warranted	Keys	1	Doors	5
Fuel Type	DIESEL	Service history	None		
Colour	BLACK	MOT Due	10/11/2026		

NO SERVICE Possible misfire
Boot will not stay open

Tyres		
NSF	BUDGET	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: B Post ns
Dented
Over 30mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osf
Scratched
Over 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Dented
Over 30mm



18: Wheel osf
Scratched
Over 50mm



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: Wing osf
Scratched
Over 25mm Thru Paint



21: A Post os
Scratched
Over 25mm Thru Paint



22: Roof
Chipped
1 To 5



23: Door Pad osf
Scuffed
Over 25mm



24: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK