



VEHICLE INSPECTION REPORT

RO59NLM

Audi A4 2.0 TDI 143 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/10/2009	Body Style	Estate	Last service miles	37,970
Year	2009	Keys	2	MOT Due	28/01/2027
Mileage	179,416 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	2	Doors	5
VIN	WAUZZZ8K8AA047857	Last service date	21/06/2012		

£90 ADDITIONAL FEE

last service 21/6/12 @ 37,970 miles (2 main dealer) Engine tapping possible misfire

Tyres

NSF	FALKEN	5.0mm
NSR	ROYALBLACK	5.0mm
OSF	RAPID	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- PAS
- Digital radio
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
 Scratched
 Over 50mm



4: Wing nsf
 Dented
 Between 10mm + 30mm



5: Door Mirror Assy nsf
 Scratched (Painted)
 UpTo 25mm Thru Paint



6: Door nsf
 Dented
 Between 10mm + 30mm



7: Door nsf
 Scratched
 UpTo 25mm Thru Paint



8: Door nsr
 Dented
 Over 30mm



9: Qtr Panel nsr
Rusted
Over 5mm



10: Wheel nsr
Scratched
Over 50mm



11: Lamp osr
Broken
Replace



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5




14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Chipped
1 To 5



20: Sill ns
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK