



VEHICLE INSPECTION REPORT

EJ61UUM

Audi A5 2.0 TDI 143 S Line 5dr Multitronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/11/2011	Keys	2	CAP Clean	£1,775.00
Year	2011	Service history	Yes	CAP Average	£1,475.00
Mileage	139,093 Miles Warranted	Service documents	Printout	CAP Below	£1,150.00
Fuel Type	DIESEL	Number of stamps	11	Gearbox	CVT
Colour	SILVER	Last service date	03/07/2025	Gears	8
VIN	WAUZZZ8T4BA104243	Last service miles	128,791	Doors	5
Body Style	Hatchback	MOT Due	03/12/2026		

£90 ADDITIONAL FEE

LAST SERVICE 03/07/2025 @ 128,791 MILES (11 SERVICES) Parking sensors faulty

Tyres

NSF	COMFORSER	4.0mm
NSR	BUDGET	5.0mm
OSF	HANKOOK	Damaged
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
With Paint Damage



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Poor Previous Repair
Poor Paint



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Dented
Over 30mm



12: Door nsf
Dented
With Paint Damage



13: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Dented
With Paint Damage



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bumper Front
Insecure
Action Required



18: Bonnet
Chipped
Multiple Chips



19: A Post os
Chipped
1 To 5



20: Roof
Scratched
Over 25mm Thru Paint



21: Door Pad osf
Broken
Replace



22: Carpets Front
Holed
Over 3mm



23: Tyre osf
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK