



VEHICLE INSPECTION REPORT

BT14XMR

Ford Fiesta 1.0 EcoBoost 125 Zetec S 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/06/2014	VIN	WF0CXXGAKCEJ49663	Gearbox	MANUAL
Year	2014	Body Style	Hatchback	Gears	5
Mileage	105,150 Miles Warranted	Keys	1	Doors	3
Fuel Type	PETROL	Service history	None		
Colour	WHITE	MOT Due	09/04/2027		

NO SERVICE HISTORY Eml light is on car been plugged in and detected catalysts system efficiency below threshold (Bank 1)

Tyres

NSF	SUNNY	5.0mm
NSR	SUNNY	5.0mm
OSF	SUNNY	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Seat Back Cover nsf
Burn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Other
N/A
N/A



5: Wing nsf
Dented
Between 10mm + 30mm



6: Wing nsf
Chipped
1 To 5



7: Wheel nsf
Scratched
Over 50mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Chipped
1 To 5



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Roof
Dented
Over 30mm



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osf
Chipped
Over 5mm



16: Door osf
Chipped
Edge Chip



17: Door osf
Dented
Between 10mm + 30mm



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Cracked
Replace



22: Roof
Chipped
Edge Chip



23: Centre Console Front
Scuffed
Over 25mm



24: Roof Lining
Burn
Over 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK