



VEHICLE INSPECTION REPORT

LG13XHP

Kia Ceed 1.6 CRDi 3 EcoDynamics 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/04/2013	Body Style	Hatchback	Last service miles	153,135
Year	2013	Keys	2	MOT Due	22/04/2027
Mileage	157,611 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	13	Doors	5
VIN	U5YHN516LDL067374	Last service date	23/03/2026		

£100 ADDITIONAL FEE

last service 23/3/26 @ 153,135 miles (13 services 7 main dealer) Low clutch, gears are stiff

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm



2: Seat Base Cover osf
Torn
UpTo 3mm



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Dented
Over 30mm



5: Door osf
Chipped
Edge Chip



6: Door osf
Dented
Between 10mm + 30mm



7: Door osr
Dented
2 Or Less UpTo 10mm



8: Wheel osr
Scratched
Up To 50mm



9: Qtr Panel osr
Chipped
1 To 5



10: Bumper Rear
Poor Previous Repair
Poor Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Chipped
1 To 5



14: Door nsr
Chipped
1 To 5



15: Door nsf
Chipped
Edge Chip



16: Door nsf
Chipped
1 To 5




17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Scratched
25 to 100mm Thru Paint



19: Bumper Front
Chipped
Multiple Chips



20: Bonnet
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm

22: A Post os
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK