



VEHICLE INSPECTION REPORT

DN68XJP

Vauxhall Mokka X 1.4T ecoTEC Active 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	23/11/2018	Body Style	Hatchback	Last service miles	101,867
Year	2018	Keys	2	MOT Due	22/11/2026
Mileage	110,302 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Electronic / Online	Gears	6
Colour	WHITE	Number of stamps	4	Doors	5
VIN	W0VJC7E82KB749236	Last service date	18/12/2025		

£90 ADDITIONAL FEE

LAST SERVICE 18/12/2025 @ 101,867 (4 SERVICES, CONFIRMED BY C&D AUTOS ASHFORD)

Eml light is on car been plugged in and detected system too lean bank 1

Tyres

NSF	RAPID	3.0mm
NSR	KUMHO	5.0mm
OSF	RAPID	3.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
Between 10mm + 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
Between 10mm + 30mm



13: Door osr
Chipped
Edge Chip



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
1 To 5



16: Wheel osf
Scratched
Up To 50mm



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK