



VEHICLE INSPECTION REPORT

GY65VVF

Kia Venga 1.6 CRDi ISG 4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/11/2015	Body Style	Hatchback	Last service miles	82,870
Year	2015	Keys	2	MOT Due	Expired
Mileage	87,534 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	9	Doors	5
VIN	U5YEH814LGL129046	Last service date	22/11/2024		

£100 ADDITIONAL FEE Last service 22/11/2024 @ 82870 miles (9 MAIN DEALER SERVICES) Sun roof catches while closing

Tyres

NSF	GT RADIAL	2.0mm
NSR	GT RADIAL	5.0mm
OSF	GT RADIAL	5.0mm
OSR	GT RADIAL	5.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Digital radio
- Opening panoramic glass roof
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



4: Wing osf
Chipped
1 To 5

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel osf
Scratched
Over 50mm



6: Door osf
Chipped
1 To 5

No Image



8: Door osr
Chipped
Multiple Chips

7: Door osf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Chipped
1 To 5

No Image

10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Cracked
UpTo 25mm

No Image

12: Boot Lid
Scratched
Over 25mm Not Thru Paint




13: Qtr Panel nsr
Dented
Over 30mm




14: Door nsr
Scratched
Over 25mm Thru Paint



15: Door nsf
Chipped
1 To 5



16: Door nsf
Scratched
Over 25mm Not Thru Paint



17: Wing nsf
Scratched
Over 25mm Not Thru Paint



18: Wheel nsf
Scratched
Up To 50mm



19: Wheel nsr
Scratched
Over 50mm



20: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		