



VEHICLE INSPECTION REPORT

WR66XKX

Ford Kuga 2.0 TDCi 180 Titanium X Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/11/2016	Body Style	Hatchback	Last service miles	112,702
Year	2016	Keys	1	MOT Due	08/04/2027
Mileage	112,760 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	1	Doors	5
VIN	WF0AXXWPMAGA43805	Last service date	10/08/2026		

LAST SERVICE 10/08/2026 @ 112,702 MILES (1 SERVICE) EmLight is on car been plugged in and detected turbocharger boost control position sensor A performance- stuck low

Tyres

NSF	HANKOOK	5.0mm
NSR	NEXEN	5.0mm
OSF	CONTINENTAL	4.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Radio/CD
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Service indicator
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door osr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate Trim Panel
Scratched (Painted)
UpTo 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
Edge Chip



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



17: Wheel osf
Scratched
Over 50mm



18: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK