



VEHICLE INSPECTION REPORT

DX63ONM

Toyota Prius+ 1.8 VVTi T4 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/09/2013	Body Style	MPV	Last service miles	120,089
Year	2013	Keys	2	MOT Due	15/09/2026
Mileage	141,974 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	1
Colour	BLACK	Number of stamps	3	Doors	5
VIN	JTDZS3EUX03061157	Last service date	20/05/2025		

£90 ADDITIONAL FEE

Last service 20/05/2025 at 120,089 miles- 3 main dealer services

Tyres


NSF	BUDGET	6.0mm
NSR	FARROAD	5.0mm
OSF	BUDGET	6.0mm
OSR	FARROAD	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5



2: Wheel of
Corroded
Light



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Dented
With Paint Damage



8: Door osr
Chipped
Edge Chip



9: Bumper Rear
Scratched
Up To 25mm Thru Paint



10: Tailgate
Chipped
1 To 5



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Door nsr
Scratched
UpTo 25mm Thru Paint



13: Door nsr
Chipped
1 To 5



14: Door nsf
Dented
Over 30mm



15: Wheel nsf
Corroded
Light



16: Wing nsf
Chipped
1 To 5




17: Bumper Front
Scratched
25 to 100mm Thru Paint



18: Bumper Front
Chipped
Multiple Chips



19: Bonnet
Chipped
1 To 5



20: Screen Front
Chipped
Over 10mm



21: Roof
Dented
Over 30mm



22: Wheel Trim osf
Missing
Replace



23: Wheel Trim nsf
Missing
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK