



VEHICLE INSPECTION REPORT

LK21FGZ

Skoda Kodiaq 1.5 TSI SE Drive 5dr DSG [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/03/2021	Body Style	Estate	Last service miles	24,294
Year	2021	Keys	2	MOT Due	24/03/2027
Mileage	51,485 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	2	Doors	5
VIN	TMBKB7NS9M8043507	Last service date	14/03/2024		

£100 ADDITIONAL FEE, LAST SERVICE 16-03-2024 @24294 MILES (2 SERVICES)


Tyres

NSF	PIRELLI	5.0mm
NSR	SUPERIA	5.0mm
OSF	NEXEN	6.0mm
OSR	SUPERIA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Dented
With Paint Damage



3: Door osr
 Scratched
 UpTo 25mm Thru Paint



4: Door osr
 Chipped
 1 To 5



5: Door osf
 Scratched
 UpTo 25mm Thru Paint



6: Wheel osr
 Corroded
 Light



7: Door osr
 Chipped
 Edge Chip



8: Bumper Rear
 Chipped
 Multiple Chips



9: Bumper Rear
Scratched
Up To 25mm Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Scratched
Up To 25mm Thru Paint



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Cracked
Replace



17: Roof
Chipped
1 To 5



18: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK