



VEHICLE INSPECTION REPORT

GK16XRM

Ford Ecosport 1.5 TDCi 95 Titanium 5dr [17in]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	31/03/2016	VIN	WF0BXXMRKBFT84047	Gearbox	MANUAL
Year	2016	Body Style	Hatchback	Gears	5
Mileage	92,305 Miles Warranted	Keys	2	Doors	5
Fuel Type	DIESEL	Service history	None		
Colour	BLACK	MOT Due	24/08/2027		

£90 ADDITIONAL FEE
NO SERVICE HISTORY Parking sensors faulty


Tyres		
NSF	ROVELO	6.0mm
NSR	BUDGET	5.0mm
OSF	ROVELO	6.0mm
OSR	ROTALLA	Punctured
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Chipped
1 To 5




16: Door osr
Chipped
1 To 5



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Door nsf
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK