

VEHICLE INSPECTION REPORT

OU67YSJ

Fiat 500 1.2 Pop 3dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		grape Grape
		V5	Present		
Details					
Reg. date	28/02/2018	Keys	1	CAP Clean	£3,625.00
Year	2018	Service history	Yes	CAP Average	£3,100.00
Mileage	58,785 Miles Warranted	Service documents	Printout	CAP Below	£2,575.00
		Number of stamps	1	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	01/12/2022	Gears	5
Colour	RED	Last service miles	36,426	Doors	3
VIN	ZFA3120000J921865	MOT Due	30/10/2025		
Body Style	Hatchback		23. 13. 2		

£65 ADDITIONAL FEE Last service 01/12/2022 @ 36426 miles (1 SERVICE)

NSF	MAXXIS	4.0mm	
NSR	BUDGET	2.0mm	
OSF	BUDGET	3.0mm	
OSR	SUNNY	4.0mm	
Spare			

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radioClimate controlSolid Paint
- Passenger airbagCloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- ABSSide airbagsSteel wheels
- Steering wheel mounted controls
 Electric door mirrors
- Front head restraints
- Drivers airbagCentral locking

Photos










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wing osf Scratched UpTo 25mm Thru Paint

No Image

5: Wing osf Scratched Over 25mm Not Thru Paint



6: Door osf Chipped 1 To 5

No Image

7: Door osf Scratched Over 25mm Not Thru Paint



8: Qtr Panel osr Chipped 1 To 5

No Image

9: Qtr Panel osr Scratched Over 25mm Not Thru Paint



10: Bumper RearScratched25 to 100mm Thru Paint

No Image

11: Bumper Rear Scratched Over 25mm Not Thru Paint



13: Qtr Panel nsr Dented Over 2 UpTo 10mm

No Image

12: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

14: Qtr Panel nsrScratchedOver 25mm Not Thru Paint



15: Door nsfChipped1 To 5



16: Wing nsf Scratched Over 25mm Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs O		Gearbox 1st and Reverse Test	
Brakes		Clutch Slip Test from Static	
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated OK		Service indicator light illuminated	OK
ABS light illuminated OK			
· ·			
Windows	OK	Radio	OK
		Steering	OK