



VEHICLE INSPECTION REPORT

GD64LZK

Lexus CT 200h 1.8 Luxury 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/01/2015	Body Style	Hatchback	Last service miles	65,430
Year	2015	Keys	2	MOT Due	19/01/2027
Mileage	65,798 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	GREY	Number of stamps	12	Doors	5
VIN	JTHKD5BH702212362	Last service date	09/07/2026		

LAST SERVICE 09-07-2026 @ 65430 MILES (12 MAIN DEALER SERVICES)

Tyres


NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	Damaged
OSF	YOKOHAMA	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Qtr Panel nsr
Dented
Between 10mm + 30mm



4: Wheel nsr
Scratched
Over 50mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Door nsr
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
Over 100mm Thru Paint




10: Door osf
Chipped
1 To 5



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Qtr Panel osr
Chipped
1 To 5



16: Door osf
Dented
Between 10mm + 30mm



17: Door osr
Chipped
1 To 5



18: Wing osf
Dented
2 Or Less UpTo 10mm



19: Wing osr
Chipped
1 To 5



20: Tyre nsr
Damaged
Replace



21: Wing nsf
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK