



VEHICLE INSPECTION REPORT

GY10AAU

Volkswagen Touran 1.9 TDI Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/03/2010	Body Style	MPV	Last service miles	118,209
Year	2010	Keys	2	MOT Due	19/03/2027
Mileage	125,778 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	11	Doors	5
VIN	WVGZZZ1TZA080102	Last service date	16/07/2025		

£100 additional fee

Last Service - 16.07.25 at 118209 miles (11 services)

Turbocharger replaced 24.09.21 at 96432 miles

cambelt and water pump replaced 05.03.21 at 93581 miles Engine noisy

Tyres


NSF	MAXXIS	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	MAXXIS	5.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door osr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Poor Previous Repair
Poor Paint



11: C Post os
Dented
Between 10mm + 30mm



12: Wheel osr
Scratched
Over 50mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Dented
Over 30mm




15: Door osf
Chipped
1 To 5



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK