



VEHICLE INSPECTION REPORT

GY16HFL

Nissan Qashqai 1.6 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/05/2016	Body Style	Hatchback	Last service miles	118,645
Year	2016	Keys	2	MOT Due	30/04/2027
Mileage	120,980 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9	Doors	5
VIN	SJNFCAJ11U1699943	Last service date	28/04/2026		

LAST SERVICE- 28-04-2026 @118645 MILES (9 SERVICES) Steering knocking

Tyres




NSF	YOKOHAMA	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Auxiliary input socket
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking

Photos





Condition Check



Damage Photos




1: Screen Front
Cracked
Replace



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Chipped
1 To 5



8: A Post ns
Chipped
1 To 5




9: Door nsf
Dented
2 Or Less UpTo 10mm




10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Dented
Between 10mm + 30mm




12: Door nsr
Chipped
1 To 5




13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



16: Bumper Rear
Scratched
25 to 100mm Thru Paint




17: Tailgate
Scratched
Over 25mm Thru Paint



18: Wheel osr
Corroded
Light



19: Qtr Panel osr
Chipped
1 To 5



20: Door osr
Scratched
Over 25mm Thru Paint



21: Door osf
Chipped
Edge Chip



22: Door osr
Dented
2 Or Less UpTo 10mm



23: Door osf
Dented
Between 10mm + 30mm





24: Wing osf
Dented
Over 30mm



25: Wing osf
Scratched
UpTo 25mm Thru Paint



26: Wheel osf
Scratched
Over 50mm



27: B Post os
Scratched
UpTo 25mm Thru Paint

28: Fogdriving Lamp osf
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK