



VEHICLE INSPECTION REPORT

SL67ZGM

Hyundai I20 1.4 SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2017	Body Style	Hatchback	Last service miles	18,245
Year	2017	Keys	2	MOT Due	21/10/2026
Mileage	20,159 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	4
Colour	GREY	Number of stamps	7	Doors	5
VIN	NLHB351CMJZ377984	Last service date	08/10/2025		

MOT MILEAGE DISCREPANCY 28/09/2023
LAST SERVICE 08/10/2025 @ 18,245 MILES (7 SERVICES)

Tyres

NSF	HANKOOK	6.0mm
NSR	HANKOOK	6.0mm
OSF	HANKOOK	6.0mm
OSR	HANKOOK	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check




Damage Photos



1: Other
N/A
N/A




2: Bonnet
Scratched
Over 25mm Thru Paint




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Between 10mm + 30mm




6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Dented
Between 10mm + 30mm



15: Qtr Panel osr
Chipped
1 To 5



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Between 10mm + 30mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
With Paint Damage



20: Sill os
Dented
With Paint Damage



21: Wing osf
Dented
With Paint Damage



22: Wheel osf
Scratched
Over 50mm



23: Screen Front
Scratched
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK