



VEHICLE INSPECTION REPORT

GN71NEJ

Mazda CX-30 2.0 e-Skyactiv X MHEV GT Sport Tech 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/09/2021	Keys	2	CAP Clean	£11,800.00
Year	2021	Service history	Yes	CAP Average	£10,600.00
Mileage	69,728 Miles Warranted	Service documents	Service Book	CAP Below	£9,425.00
Fuel Type	PETROL	Number of stamps	5	Gearbox	AUTOMATIC
Colour	RED	Last service date	30/09/2025	Gears	6
VIN	JMZDM6WHA00200962	Last service miles	55,759	Doors	5
Body Style	Hatchback	MOT Due	29/09/2026		

Last Service - 30.09.2025 at 55759 miles (5 main dealer services)

Tyres

NSF	KORMORAN	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	KORMORAN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Front
Dented
With Paint Damage



2: Bonnet
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: B Post ns
Dented
Between 10mm + 30mm



8: Tailgate
Chipped
1 To 5



9: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm




10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Chipped
Edge Chip



14: Door Mirror Assy osf
Broken
Replace



15: Wheel osf
Dented
UpTo 30mm (Alloy)



16: Wing osf
Scratched
UpTo 25mm Thru Paint



17: Roof
Scratched
UpTo 25mm Thru Paint



18: Screen Front
Cracked
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK