



VEHICLE INSPECTION REPORT

GX17ODV

Vauxhall Viva 1.0 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/03/2017	Keys	2	CAP Clean	£2,475.00
Year	2017	Service history	Yes	CAP Average	£2,025.00
Mileage	52,941 Miles Warranted	Service documents	Service Book	CAP Below	£1,575.00
Fuel Type	PETROL	Number of stamps	6	Gearbox	MANUAL
Colour	RED	Last service date	27/02/2023	Gears	5
VIN	W0LDD6E73HC779546	Last service miles	34,574	Doors	5
Body Style	Hatchback	MOT Due	04/03/2027		

£100 additional fee

LAST SERVICE 27/02/2023 @ 34,574 MILES (6 SERVICES) Eml light is on
Car been plugged in and detected crankshaft position correlation

Tyres

NSF	BUDGET	5.0mm
NSR	WESTLAKE	5.0mm
OSF	TRIANGLE	4.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Folding rear seats
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Media storage
- Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Steel wheels
- Rear wiper
- Electric door mirrors
- Height adjustable drivers seat
- ABS
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front Moulding
Broken
Replace




5: Wing nsf
Poor Previous Repair
Poor Paint



6: Handle Outer nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsr
Dented
Over 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Bumper Rear
Scratched
Up To 25mm Thru Paint




11: Tailgate
Dented
Over 30mm



12: Aerial
Broken
Replace



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK