

VEHICLE INSPECTION REPORT

KM64VDE

Citroen C4 Picasso 1.6 HDi VTR+ 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	10/12/2014	Colour	WHITE	MOT Due	20/08/2027
Year	2014	VIN	VF73D9HP0EJ823252	Gearbox	MANUAL
Mileage	119,135 Miles Warranted	Body Style	MPV	Gears	5
Fuel Type	DIESEL	Keys	1	Doors	5

No Service History


Tyres

NSF	COMPASSAL	Punctured
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	DAVANTI	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: A Post ns
Chipped
1 To 5



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Rusted
Over 5mm



7: Door osf
Dented
Between 10mm + 30mm



8: Door nsr
Dented
With Paint Damage



9: Door nsf
Chipped
Over 5mm



10: Qtr Panel nsr
Rusted
Over 5mm



11: Wheel nsr
Corroded
Light



12: Bumper Rear
Dented
With Paint Damage



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Wheel osr
Corroded
Light



15: Qtr Panel osr
Rusted
Over 5mm



16: Sill os
Dented
Over 30mm



17: Door osr
Chipped
Over 5mm




18: Door osf
Rusted
Over 5mm



19: Wing osf
Scratched
Rusted



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

22: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK